

Rating form
completed by:**RUTHERFORD + CHEKENE**
ruthchek.com

Evaluator: BL

Date: 06/28/2019

Text in *green* is to be part of UC Santa Cruz building database and may be part of UCOP database

DATE: 2018-06-28

UC Santa Cruz building seismic ratings
EBASK Building D

CAAN #7496

433 Baskin Arts Service Road, Santa Cruz, CA 95064

UCSC Campus: Main Campus



Southwest Elevation (Looking Northeast)



Plan



| Rating summary | Entry | Notes |
|--|-----------|--|
| UC Seismic Performance Level (rating) | IV (Fair) | |
| Rating basis | Level 1 | FEMA P-154 ¹ |
| Date of rating | 2019 | |
| Recommended UC Santa Cruz priority category for retrofit | None | Priority A=Retrofit ASAP Priority B=Retrofit at next permit application |
| Ballpark total construction cost to retrofit to IV rating ² | None | |
| Is 2018-2019 rating required by UCOP? | Yes | Building was not previously rated |
| Further evaluation recommended? | No | |

¹ We translate this FEMA 154 evaluation to a Seismic Performance Level rating using professional judgment. Non-compliant items or a certain score in the FEMA 154 evaluation do not automatically put a building into a particular rating category, but we evaluate such items along with the combination of building features and potential deficiencies, focused on the potential for collapse or serious damage to the gravity supporting structure that may threaten occupant safety. See Section III.B of the 19 May 2017 *UC Seismic Safety Policy* and Method B of Section 321 of the 2016 *California Building Code*.

² Per Section III.A.4.i of the 26 March 2019 *UC Seismic Program Guidebook, Version 1.3*, the cost includes all construction cost necessitated by the seismic retrofit, including restoration of finishes and any triggered work on utilities or accessibility. It does not include soft costs such as design fees or campus costs. The cost is in 2019 dollars.

Building information used in this evaluation

- Architectural drawings by Marquis Associates Architecture/Planning/Interior/Design, "University of California at Santa Cruz Visual Arts Facilities," dated 14 December 1983, Sheets A1.1 to A1.10, A2.1 to A2.4, A3.1 to A3.4, A4.1, A5.1, A5.2, A6.1, A7.1, A7.2.
- Structural drawings by Ephraim Hirsch & Associates, "University of California at Santa Cruz Visual Arts Facilities," as-built dated 14 December 1983, Sheets S-1 to S-8.

Additional building information known to exist

- None

Scope for completing this form

The architectural and structural drawings were reviewed, a brief site observation was made on 23 May 2019, and a FEMA P-154 Level 1 evaluation was completed.

Brief description of structure

The Elena Baskin Visual Arts Studios Building D is a wood framed building with a gable roof. It is located within the Elena Baskin Visual Arts Studios on the main UC Santa Cruz campus. It is rectangular in shape and measures 32'-8" in the northeast-southwest direction by 28'-0" in the northwest-southeast direction. The structure is located on a sloping site with grade at a high point on the southwest elevation and a low point on the northeast elevation. The grade changes by approximately a full story height. It has one-story above grade and a partial basement below grade. The at-grade story is utilized as a classroom and the below grade story contains a small electrical room. The structure is approximately 1,400 square feet. It is not eligible to be benchmarked because it is located on a sloping site with a full story height and contains narrow wall piers on the basement exterior wall.

The floor is framed with 2 x 12 wood joists spaced at 16" o.c that span in the northwest-southeast direction to the exterior walls. The roof is clad with metal standing seam roofing over 3/8" plywood sheathing that is supported by wood joists. The joists consist of 2 x 10 framing spaced at 24" o.c. that span between the exterior wood walls and steel and wood truss located at the ridge of the roof. The exterior walls are framed with 5/8" plywood sheathing over 2 x 6 wood studs. The building walls are clad with vertical wood sliding on the exterior. In general, the structure appears to be in good condition.

Brief description of seismic deficiencies and expected seismic performance including mechanism of nonlinear response and structural behavior modes

Identified seismic deficiencies of the building include the following:

- The structure location meets the definition of a hillside site/sloping site. The one-story above grade walls are stiffer than the two-story tall wall located on the site downslope. However, the extent of wall on the downslope side is considered sufficient for the relatively small size of the building.

FEMA P-154 Score

| BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1} | | | | | | | | | | | | | | | | | | |
|---|-------------|------------|------------|------------|------------|------------|------------|------------|--------------|------------|------------|--------------|------------|------------|------------|------------|------------|------------|
| FEMA BUILDING TYPE | Do Not Know | W1 | W1A | W2 | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2 | RM1 (FD) | RM2 (RD) | URM | MH |
| Basic Score | | 2.1 | 1.9 | 1.8 | 1.5 | 1.4 | 1.6 | 1.4 | 1.2 | 1.0 | 1.2 | 0.9 | 1.1 | 1.0 | 1.1 | 1.1 | 0.9 | 1.1 |
| Severe Vertical Irregularity, V_{L1} | | -0.9 | -0.9 | -0.9 | -0.8 | -0.7 | -0.8 | -0.7 | -0.7 | -0.7 | -0.8 | -0.7 | -0.7 | -0.7 | -0.7 | -0.7 | -0.6 | NA |
| Moderate Vertical Irregularity, V_{L2} | | -0.6 | -0.5 | -0.5 | -0.4 | -0.4 | -0.5 | -0.4 | -0.3 | -0.4 | -0.4 | -0.3 | -0.4 | -0.4 | -0.4 | -0.4 | -0.3 | NA |
| Plan Irregularity, P_{L1} | | -0.7 | -0.7 | -0.6 | -0.5 | -0.5 | -0.6 | -0.4 | -0.4 | -0.4 | -0.5 | -0.3 | -0.5 | -0.4 | -0.4 | -0.4 | -0.3 | NA |
| Pre-Code | | -0.3 | -0.3 | -0.3 | -0.2 | -0.2 | -0.3 | -0.2 | -0.1 | -0.1 | -0.2 | 0.0 | -0.2 | -0.1 | -0.2 | -0.2 | 0.0 | 0.0 |
| Post-Benchmark | | 1.9 | 1.9 | 2.0 | 1.0 | 1.1 | 1.1 | 1.5 | NA | 1.4 | 1.7 | NA | 1.5 | 1.7 | 1.6 | 1.6 | NA | 0.5 |
| Soil Type A or B | | 0.5 | 0.5 | 0.4 | 0.3 | 0.3 | 0.4 | 0.3 | 0.2 | 0.2 | 0.3 | 0.1 | 0.3 | 0.2 | 0.3 | 0.3 | 0.1 | 0.1 |
| Soil Type E (1-3 stories) | | 0.0 | -0.2 | -0.4 | -0.3 | -0.2 | -0.2 | -0.2 | -0.1 | -0.1 | -0.2 | 0.0 | -0.2 | -0.1 | -0.2 | -0.2 | 0.0 | -0.1 |
| Soil Type E (> 3 stories) | | -0.4 | -0.4 | -0.4 | -0.3 | -0.3 | NA | -0.3 | -0.1 | -0.1 | -0.3 | -0.1 | NA | -0.1 | -0.2 | -0.2 | 0.0 | NA |
| Minimum Score, S_{MIN} | | 0.7 | 0.7 | 0.7 | 0.5 | 0.5 | 0.5 | 0.5 | 0.5 | 0.3 | 0.3 | 0.3 | 0.2 | 0.2 | 0.3 | 0.3 | 0.2 | 1.0 |
| FINAL LEVEL 1 SCORE, $S_{L1} \geq S_{MIN}$: | | 1.5 | | | | | | | | | | | | | | | | |
| UCOP SEISMIC PERFORMANCE LEVEL (OR "RATING") IV | | | | | | | | | | | | | | | | | | |

Summary of review of nonstructural life-safety concerns, including at exit routes.³

No falling hazards that pose a risk to the building occupants were observed.

| UCOP nonstructural checklist item | Life safety hazard? | UCOP nonstructural checklist item | Life safety hazard? |
|--|---------------------|--|---------------------|
| Heavy ceilings, feature or ornamentation above large lecture halls, auditoriums, lobbies or other areas where large numbers of people congregate | None observed | Heavy partitions braced by ceilings | None observed |
| Heavy masonry or stone veneer above exit ways and public access areas | None observed | Appendages | None observed |
| Unbraced masonry parapets, cornices or other ornamentation above exit ways and public access areas | None observed | Unrestrained hazardous materials storage | None observed |
| Masonry chimneys | None observed | Unrestrained natural gas-fueled equipment such as water heaters, boilers, emergency generators, etc. | None observed |

Discussion of rating

Although the building is located on a sloping site, it is rated IV as the building proportions are approximately square, it is well-detailed, in good condition, and the walls do not contain significant openings and demands are anticipated to be relatively low.

Recommendations for further evaluation or retrofit

No further analysis is required.

Peer review of rating

This seismic evaluation was discussed in a peer review meeting on 28 May 2019. Reviewers present were Joe Maffei of Maffei Structural Engineering and Holly Razzano and Jay Yin of Degenkolb Engineers. Comments from the reviewers have been incorporated into this report. The reviewers agreed with the assigned rating.

³ For these Tier 1 evaluations, we do not visit all spaces of the building; we rely on campus staff to report to us their understanding of if and where nonstructural hazards may occur.

| Additional building data | Entry | Notes |
|--|-------------------------------|------------------------------------|
| Latitude | 36.99475 | |
| Longitude | -122.060600 | |
| Are there other structures besides this one under the same CAAN# | No | |
| Number of stories above lowest perimeter grade | 2 | |
| Number of stories (basements) below lowest perimeter grade | 0 | |
| Building occupiable area (OGSF) | 1,404 | |
| Risk Category per 2016 CBC Table 1604.5 | II | Classroom |
| Site data | | |
| Site class | D | |
| Site class basis | Geotech ⁴ | See footnote below |
| Liquefaction potential | Low | |
| Liquefaction assessment basis | County map | See footnote below |
| Landslide potential | Low | |
| Landslide assessment basis | County map | See footnote below |
| Active fault rupture identified at site? | No | |
| Fault rupture assessment basis | County map | See footnote below |
| Applicable code | | |
| Applicable code or approx. date of original construction | Built: 1984 Code: 1982 UBC | Code inferred based on design year |
| Applicable code for partial retrofit | None | No partial retrofit |
| Applicable code for full retrofit | None | No full retrofit |
| Model building data | | |
| Model building type North-South | | |
| Model building type East-West | | |
| FEMA P-154 score | 1.5 | |
| Previous ratings | | |
| Most recent rating | None | |
| Date of most recent rating | | |

⁴ Determination of site class and assessment of geotechnical hazards are based on correspondence with Pacific Crest Geotechnical Engineers and Nolan, Zinn, and Associates Geologists. [*Revised Geology and Geologic Hazards, Santa Cruz Campus, University of California*, Job # 04003-SC 13 May 2005]. Site class is taken as D throughout the main campus of UC Santa Cruz. The following links provide hazard maps for liquefaction, landslide, and fault rupture:

<https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LiquifactionMap2009.pdf>

<https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LandslideMap2009.pdf>

<https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/FaultZoneMap2009.pdf>

| | |
|--|---|
| 2 nd most recent rating | - |
| Date of 2 nd most recent rating | - |

| | |
|--|---|
| 3 rd most recent rating | - |
| Date of 3 rd most recent rating | - |

| | |
|---|--|
| Report attachments | |
| P-154 Level 1 Form and Additional Photos | |



APPENDIX A

FEMA P-154 Form and Additional Photos



Rapid Visual Screening of Buildings for Potential Seismic Hazards
FEMA P-154 Data Collection Form

Level 1
VERY HIGH Seismicity



Southwest facade (looking northeast)

Address: 433 Baskin Arts Service Road
Santa Cruz, CA Zip: 95064

Other Identifiers: CAAN 7496

Building Name: _____

Use: Classroom

Latitude: 36.99475 Longitude: -122.060600

S_s: 1.468g (MCE_R, Site Class B) S_i: 0.50g (MCE_R, Site Class B)

Screener(s): Emma Meehan/Jorge Moreno Date/Time: 5/23/19 / 9:32AM

No. Stories: Above Grade: 1 Below Grade: 1 Year Built: 1984 EST

Total Floor Area (sq. ft.): 1,404 Code Year: 1982

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor
Rock Rock Soil Soil Soil Soil
If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes No DNK Landslide: Yes No DNK Surf. Rupt.: Yes No DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) Sloping site/severe
 Plan (type) _____

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____

COMMENTS:

- Plywood sheathed stud-frame walls function as the vertical load-carrying system and the lateral force-resisting system.
- Site is sloping down to the northeast, leading to a the full story grade change from one side of the building to the other.
- Plan dimensions of the lower floor are smaller than the upper floor due to the sloping site. Intermediate wall at soil interface at lower floor does not extend to story above.
- Note that FEMA P-154 uses the MCE_R Site Class B site parameters to determine the Seismicity Region. The Very High Seismicity Region applies here since S_s = 1.5 >= 1.5.

Additional sketches or comments on separate page

SKETCH

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

| FEMA BUILDING TYPE | Do Not Know | W1 | W1A | W2 | S1 (MRF) | S2 (BR) | S3 (LM) | S4 (RC SW) | S5 (URM INF) | C1 (MRF) | C2 (SW) | C3 (URM INF) | PC1 (TU) | PC2 | RM1 (FD) | RM2 (RD) | URM | MH |
|---|-------------|------|------|------|----------|---------|---------|------------|--------------|----------|---------|--------------|----------|------|----------|----------|------|----|
| Basic Score | <u>2.1</u> | 1.9 | 1.8 | 1.5 | 1.4 | 1.6 | 1.4 | 1.2 | 1.0 | 1.2 | 0.9 | 1.1 | 1.0 | 1.1 | 1.1 | 0.9 | 1.1 | |
| Severe Vertical Irregularity, V _{L1} | -0.9 | -0.9 | -0.9 | -0.8 | -0.7 | -0.8 | -0.7 | -0.7 | -0.7 | -0.7 | -0.8 | -0.6 | -0.7 | -0.7 | -0.7 | -0.6 | NA | |
| Moderate Vertical Irregularity, V _{L1} | <u>-0.6</u> | -0.5 | -0.5 | -0.4 | -0.4 | -0.5 | -0.4 | -0.3 | -0.4 | -0.4 | -0.3 | -0.4 | -0.4 | -0.4 | -0.4 | -0.3 | NA | |
| Plan Irregularity, P _{L1} | -0.7 | -0.7 | -0.6 | -0.5 | -0.5 | -0.6 | -0.4 | -0.4 | -0.4 | -0.5 | -0.3 | -0.5 | -0.4 | -0.4 | -0.4 | -0.3 | NA | |
| Pre-Code | -0.3 | -0.3 | -0.3 | -0.3 | -0.2 | -0.3 | -0.2 | -0.1 | -0.1 | -0.2 | 0.0 | -0.2 | -0.1 | -0.2 | -0.2 | 0.0 | 0.0 | |
| Post-Benchmark | 1.9 | 1.9 | 2.0 | 1.0 | 1.1 | 1.1 | 1.5 | NA | 1.4 | 1.7 | NA | 1.5 | 1.7 | 1.6 | 1.6 | NA | 0.5 | |
| Soil Type A or B | 0.5 | 0.5 | 0.4 | 0.3 | 0.3 | 0.4 | 0.3 | 0.2 | 0.2 | 0.3 | 0.1 | 0.3 | 0.2 | 0.3 | 0.3 | 0.1 | 0.1 | |
| Soil Type E (1-3 stories) | 0.0 | -0.2 | -0.4 | -0.3 | -0.2 | -0.2 | -0.2 | -0.1 | -0.1 | -0.2 | 0.0 | -0.2 | -0.1 | -0.2 | -0.2 | 0.0 | -0.1 | |
| Soil Type E (> 3 stories) | -0.4 | -0.4 | -0.4 | -0.3 | -0.3 | NA | -0.3 | -0.1 | -0.1 | -0.3 | -0.1 | NA | -0.1 | -0.2 | -0.2 | 0.0 | NA | |
| Minimum Score, S _{MIN} | 0.7 | 0.7 | 0.7 | 0.5 | 0.5 | 0.5 | 0.5 | 0.5 | 0.3 | 0.3 | 0.3 | 0.2 | 0.2 | 0.3 | 0.3 | 0.2 | 1.0 | |

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: 1.5

UCOP SEISMIC PERFORMANCE LEVEL (OR "RATING") IV

EXTENT OF REVIEW

Exterior: Partial All Sides Aerial
Interior: None Visible Entered

Drawings Reviewed: Yes No

Soil Type Source: Default campus site class

Geologic Hazards Source: County of Santa Cruz maps

Contact Person: _____

OTHER HAZARDS

Are There Hazards That Trigger A Detailed Structural Evaluation?

Pounding potential (unless S₂₂ > cut-off, if known)

Falling hazards from taller adjacent building

Geologic hazards or Soil Type F

Significant damage/deterioration to the structural system

ACTION REQUIRED

Detailed Structural Evaluation Required?

Yes, unknown FEMA building type or other building

Yes, score less than cut-off

Yes, other hazards present

No

Detailed Nonstructural Evaluation Recommended? (check one)

Yes, nonstructural hazards identified that should be evaluated

No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary

No, no nonstructural hazards identified DNK



LEVEL 2 SCREENING PERFORMED?

Yes, Final Level 2 Score, S_{L2} _____ No

Nonstructural hazards? Yes No

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm



Elevations from the architectural drawings



Sloping site to the northeast (looking north)




Classroom in upper floor (looking north)



Wood and steel truss below roof



Mechanical equipment at lower floor



UC Santa Cruz Map



UC Santa Cruz Map - Elena Baskin Visual Arts