



Rating form completed by:

RUTHERFORD + CHEKENE
ruthchek.com

Evaluator: JY/WAL/BL

Date: 06/28/2019

Text in green is to be part of UC Santa Cruz building database and may be part of UCOP database

DATE: 2019-06-28

UC Santa Cruz building seismic ratings
Visual Arts Facilities-Building G

CAAN #7499

Elena Baskin Visual Arts, Santa Cruz, CA 95064

UCSC Campus: Main Campus

Southeast Corner (Looking Northwest)



Plan



Rating summary	Entry	Notes
UC Seismic Performance Level (rating)	V (Poor)	
Rating basis	Tier 1	ASCE 41-17 ¹
Date of rating	2019	
Recommended list assignment (UC Santa Cruz category for retrofit)	Priority B	Priority A=Retrofit ASAP Priority B=Retrofit at next permit application
Ballpark total construction cost to retrofit to IV rating ²	Medium (\$50-200/sf)	See recommendations on further evaluation and retrofit.
Is 2018-2019 rating required by UCOP?	Yes	Building was not previously rated
Further evaluation recommended?	Yes	Focused on analysis of current wood braced frame connections and possible improvement to the seismic resistance of the building in general

¹ We translate this Tier 1 evaluation to a Seismic Performance Level rating using professional judgment. Non-compliant items in the Tier 1 evaluation do not automatically put a building into a particular rating category, but we evaluate such items along with the combination of building features and potential deficiencies, focused on the potential for collapse or serious damage to the gravity supporting structure that may threaten occupant safety. See Section III.B of the 19 May 2017 *UC Seismic Safety Policy* and Method B of Section 321 of the 2016 *California Building Code*.

² Per Section III.A.4.i of the 26 March 2019 *UC Seismic Program Guidebook, Version 1.3*, the cost includes all construction cost necessitated by the seismic retrofit, including restoration of finishes and any triggered work on utilities or accessibility. It does not include soft costs such as design fees or campus costs. The cost is in 2019 dollars.

Building information used in this evaluation

- Architectural drawings by Marquis Associates, "Visual Arts Facilities, University of California, Santa Cruz," signed 14 Dec 1983, sheets A2.2, A2.4 and A3.1-A7.2 pertinent to Building 'E', 'F', and 'G'.
- Structural drawings by E.G. Hirsch & Associates, "Visual Arts Facilities, University of California, Santa Cruz," signed 14 Dec 1983, sheets S1, S3, S5 and S6-S8 pertinent to Building 'E', 'F' and 'G'.

Additional building information known to exist

None

Scope for completing this form

Reviewed structural drawings for original construction, made brief site visit on 16 May 2019, and carried out ASCE 41-17 Tier 1 evaluation.

Brief description of structure

Baskin Building G is one of a cluster of seven similar buildings that forms the visual art studios of Department of Art at the campus. The complex was designed in 1983 by the architectural office of Marquis Associates and the structural office of E.G. Hirsch & Associates. Construction completion date is unknown.

The building is a single-story wood-frame structure that contains approximately 5,565 sf, with a canopy of approximately 1,061 sf. Counting the canopy at half yields $5,565 \text{ sf} + \frac{1}{2} \times 1,061 \text{ sf} = 5,096 \text{ sf}$. Building G is linked to Building F to the north by what used to be a covered walk but now enclosed as a print studio. There is a continuous covered walk along the west side and the west end of the south side of the building. In plan, the building is comprised of three rectangular sections, each measuring 20 ft deep by various widths. Each rectangular section is constructed with diagonal wood braced frames in the E-W direction and plywood shear walls in the N-S direction. Adjacent sections share a line of diagonal wood brace frames. The roof diaphragm of each rectangular section slopes from the upper beam of the braced frame on the north (19'-8" average elevation) to the lower beam of the braced frame on the south (8'-6" average elevation). Wood joists sloping with the roof are spaced at 16" on center and supported by braced frame beams on each end. The upper and lower braced frame beams, 5 1/8" wide x 7 1/2" deep and 5 1/8" wide x 16 1/2" deep respectively, are Douglas Fir glued laminated beam that run continuously between 6x6 end posts and over 6x8 or 8x8 interior posts. A 4" reinforced concrete slab-on-grade is observed exposed in most of the rooms.

The attached covered walk to the west of the building is constructed with plywood roof atop wood joist framing extending between exterior wall of the buildings and built-up wood posts. The floor is slab on grade exposed to weather.

Building condition: The building appears to be in relatively good condition. The viewed exposed connections and braces appeared to be generally consistent with the structural drawings.

Identification of levels: One story above slab-on-grade.

Foundation System: The perimeter walls bear on a curb supported by the thickened edge of the slab and then a continuous grade beam. The interior bearing walls are supported by the thickened slab and then a continuous grade beam. The grade beams are 1'0" wide x 1'4" minimum deep grade beam reinforced with #3 stirrups at 12" o.c. Braced frame posts are supported by 1'0"x1'0" pedestals integrated with the slab on 2'6"x2'6"x1'4" minimum deep spread footings. All wood posts, 6x6s end posts, and 6x8s intermediate posts are anchored into the concrete curbs and thickened slab with anchor bolts. In the covered walk, the built-up columns are anchored to continuous concrete grade beams below similar to the typical building perimeter.

Structural system for vertical (gravity) load: The sawtooth roof is comprised of 5/8-inch plywood sheathing spanning atop 2x10 wood joists. Joists are supported at each end to wood braced frame glulam beams with face mounted joist hangers. Glulam beams span continuously between end posts and over interior posts. Walls use 2x6 studs at 24" o.c.

The attached covered walk is framed with 2x8 wood joist framing and 5/8-inch plywood sheathing. Joists are supported by a continuous 3x8 ledger screwed to exterior wall of the building on one end and bearing on top of built-up wood beam sections on the other side. The built-up wood beams are supported by built-up columns.

The covered walk is framed with 2x8 joist framing and 5/8-inch plywood sheathing. Joists are supported by built-up wood beams on each end. These beams are supported by built-up columns.

Structural system for lateral forces: In N-S direction, lateral forces are transferred from the plywood roof diaphragm through blocking at the eave to the top plate of the plywood shear walls per Detail 6 on Sheet S-8. The 5/8" plywood has 10d at 6" o.c. edge nailing. Loads at the base of the wall go into the continuous curb from the 3x6 sill through 5/8" diameter anchor bolts at 4'0" o.c. per Detail 16 on Sheet S-7. In the E-W direction, the plywood roof diaphragm spans between the upper beam of the wood braced frame at the ridge and the lower beam of adjacent wood braced frame at the bottom of the roof slope. More specifically, at the ridge, shear in the plywood is delivered into the upper beams through 2x blocking between each rafter (Detail 1 on Sheet S-8). At the low end, the plywood is nailed to 2x blocking and which is in turn face nailed to the glulam beam. An additional path for shear transfer at the low end is through a built-up roof that has a cross-slope for drainage. Plywood sheathing wraps over the built-up roof comprised of 2x4s and then to the face of continuous parapet walls built on top of the lower beam (Detail 3 on Sheet S-8). The braced frames on Lines I and J have four "Y" shapes. The braced frames on Line K have two "Y" shapes. The top of the "Y" is connected to the top glulam beam and the midheight of the "Y" connects to the low glulam beam which in turn is connected to a plywood shear wall. A clerestory above the low beam brings northern light to the studios. The braces are connected to the center post and to the glulam with steel side plates and 3/4" diameter machine bolts typically in single shear. Details are on Sheet S-7.

At the attached covered walk, plywood sheathing stops at the inner face of the built-up columns per Detail 7 on Sheet S-8. All N-S direction lateral force is expected to be transferred through a continuous 3x8 ledger anchored to the face of the building exterior wall. In the E-W direction, lateral forces toward the building push the joists against the ledger onto the perimeter studs placing the studs in bending. When the canopy pulls away from the perimeter walls, the ledger is in cross-grain bending.

Brief description of seismic deficiencies and expected seismic performance including mechanism of nonlinear response and structural behavior modes

Identified seismic deficiencies of the building include the following:

- The braced frames rely on a complicated set of force transfer details that include bolts in shear in the wood. These details have reduced end distances (4D rather than 7D) and limited ductility compared to a plywood shear wall that dissipates energy through nails in bending, and they are ultimately likely to lead to longitudinal splitting of the wood. This is an unusual structural system not covered by the wood frame Tier 1 checklists of ASCE 41-17. A Tier 2 deficiency-based analysis of the frames, their internal connections, and their connections to the shear walls is needed to understand better the capacity and performance of this lateral force-resisting system.
- At the canopy, transverse loads pulling the canopy away from the building will place the supporting ledger at the building stud walls in cross-grain bending. This could lead to loss of gravity support.
- Building G is connected by the canopy of the walkway to Building F without any seismic separation or collectors at either end. Out-of-phase movement between the buildings could lead to loss of gravity support.
- Building G is also connected for a portion of the north side of Building G to the south side of Building F with no seismic separation or collectors. Out-of-phase movement between the buildings could lead to loss of gravity support of the north end of the

Structural deficiency	Affects rating?	Structural deficiency	Affects rating?
Lateral system stress check (wall shear, column shear or flexure, or brace axial as applicable)	Y	Openings at shear walls (concrete or masonry)	N
Load path	N	Liquefaction	N
Adjacent buildings	Y	Slope failure	N
Weak story	N	Surface fault rupture	N
Soft story	N	Masonry or concrete wall anchorage at flexible diaphragm	N
Geometry (vertical irregularities)	N	URM wall height-to-thickness ratio	N
Torsion	N	URM parapets or cornices	N
Mass – vertical irregularity	N	URM chimney	N
Cripple walls	N	Heavy partitions braced by ceilings	N
Wood sills (bolting)	N	Appendages	N
Diaphragm continuity	Y		

Summary of review of nonstructural life-safety concerns, including at exit routes.³

Light storage mezzanines inside office spaces were discovered during the brief site visit performed on 16 May 2019. Items stored on those are considered as falling hazard during an earthquake event. Lockers in the corridor should be properly braced from tipping over.

UCOP nonstructural checklist item	Life safety hazard?	UCOP nonstructural checklist item	Life safety hazard?
Heavy ceilings, feature or ornamentation above large lecture halls, auditoriums, lobbies or other areas where large numbers of people congregate	None observed	Unrestrained hazardous materials storage	None observed
Heavy masonry or stone veneer above exit ways and public access areas	None observed	Masonry chimneys	None observed
Unbraced masonry parapets, cornices or other ornamentation above exit ways and public access areas	None observed	Unrestrained natural gas-fueled equipment such as water heaters, boilers, emergency generators, etc.	None observed

Basis of rating

A Seismic Performance Level rating of V is assigned to Building G based on the absence of an ASCE 41-17 Tier 1 quick check procedure for wood braced frames, the limited ductility in the braced frames, the poor out-of-plane transfer detail at the canopy to perimeter wall that relies on cross-grain bending, and the lack of collectors tying Buildings F and G together.

Recommendations for further evaluation or retrofit

We recommend that the campus perform a Tier 2 evaluation to review the lateral force-resisting capacity of the wood braced frame members, internal connections, and connections to the plywood shear wall. While ductility is low, it may be that there is sufficient capacity due to low demands. If the braced frames were found to be inadequate, connections could be strengthened or supplemental lateral resistance could be added, such steel moment frames to help continue to preserve the clerestory light. Retrofits would also include positive anchorage at the canopy to perimeter stud walls to prevent cross-grain bending. We assign the building to Priority Category B, as the retrofit of the building should be done when there are any plans for renovation or change of occupancy. Falling hazards reduction, such as the storage mezzanines, should be addressed.

³ For these Tier 1 evaluations, we do not visit all spaces of the building; we rely on campus staff to report to us their understanding of if and where nonstructural hazards may occur.

Peer review of rating

This seismic evaluation was discussed in a peer review meeting on 28 May 2019. Reviewers present were Joe Maffei of Maffei Structural Engineering and Holly Razzano and Jay Yin of Degenkolb. Comments from the reviewers have been incorporated into this report. The reviewers agreed with the assigned rating.

Additional building data	Entry	Notes
Latitude	36.994539	
Longitude	-122.061018	
Are there other structures besides this one under the same CAAN#	No	
Number of stories above lowest perimeter grade	1	
Number of stories (basements) below lowest perimeter grade	0	
Building occupiable area (OGSF)	5,096	6,273 sf in facilities database
Risk Category per 2016 CBC Table 1604.5	II	
Estimated fundamental period	0.14 sec	Estimated using ASCE 41-17 equation 4-4 and 7-18
Building structural height, h_n	14 ft	Structural height defined per ASCE 7-16 Section 11.2
Coefficient for period, C_t	0.020	Estimated using ASCE 41-17 equation 4-4 and 7-18
Coefficient for period, β	0.75	Estimated using ASCE 41-17 equation 4-4 and 7-18
Site data		
975-year hazard parameters S_s, S_1	1.281, 0.88	From SEAOC/OSHPD website
Site class	D	
Site class basis	Geotech ⁴	See footnote below
Site parameters F_a, F_v	1.0, 1.815	From SEAOC/OSHPD website
Ground motion parameters S_{cs}, S_{c1}	1.631, 0.625	From SEAOC/OSHPD website
S_a at building period	1.28	
Site V_{s30}	900 ft/s	
V_{s30} basis	Estimated	Estimated based on site classification of D.
Liquefaction potential	Low	
Liquefaction assessment basis	County map	See footnote below
Landslide potential	Low	

⁴ Determination of site class and assessment of geotechnical hazards are based on correspondence with Pacific Crest Geotechnical Engineers and Nolan, Zinn, and Associates Geologists. [Revised Geology and Geologic Hazards, Santa Cruz Campus, University of California, Job # 04003-SC 13 May 2005]. Site class is taken as D throughout the main campus of UC Santa Cruz. The following links provide hazard maps for liquefaction, landslide, and fault rupture:


<https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LiquifactionMap2009.pdf>

<https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LandslideMap2009.pdf>


<https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/FaultZoneMap2009.pdf>

Landslide assessment basis	County map	See footnote below
Active fault rupture identified at site	No	
Fault rupture assessment basis	County map	See footnote below
Site-specific ground motion study?	No	
Applicable code		
Applicable code or approx. date of original construction	Built: 1983 Code: 1982 UBC	Code inferred based on design year
Applicable code for partial retrofit	None	No partial retrofit
Applicable code for full retrofit	None	No full retrofit
FEMA P-154 data		
Model building type North-South	W2 - Wood Frame	
Model building type East-West	Wood Braced Frame	No checklist is available in ASCE 41-17. Even though the building is wood frame and designed to a code after the 1982 UBC, the building was not benchmarked since the braced frames are not consistent with the W2 definition.
FEMA P-154 score	N/A	Not included here because we performed ASCE 41 Tier 1 evaluation.
Previous ratings		
Most recent rating	-	Not evaluated before
Date of most recent rating	-	Indicated on spreadsheet
2 nd most recent rating	-	
Date of 2 nd most recent rating	-	
3 rd most recent rating	-	
Date of 3 rd most recent rating	-	
Appendices		
ASCE 41 Tier 1 checklist included here?	Yes	Refer to attached checklist file


Color Coded Floor Plan



Example Braced Frame Elevations



Connection Detail between Main Elements of the Wood Diagonal Braced Frames





Rating form
completed by:

RUTHERFORD + CHEKENE

ruthchek.com

Evaluator: JY/WAL/BL

Date: 06/28/2019

APPENDIX A


Additional Photos



Southwest Corner of Building G (Looking Northeast)



Southeast Corner of Building G (Looking Northwest)



MEP Ducts and Equipment in Print Studio



Storage Mezzanine in Offices



Rating form
completed by:

RUTHERFORD + CHEKENE
ruthchek.com

Evaluator: JY/WAL/BL

Date: 06/28/2019

APPENDIX B

ASCE 41-17 Tier 1 Checklists

UC Campus:	Santa Cruz		Date:	06/28/2019		
Building CAAN:	7499	Auxiliary CAAN:	By Firm:	Rutherford + Chekene		
Building Name:	Elena Baskin Visual Arts Building G		Initials:	YJ	Checked:	WAL/BL
Building Address:	Santa Cruz, CA 95064		Page:	1	of	3

ASCE 41-17 Collapse Prevention Basic Configuration

ASCE 41-17 Tier 1 Checklists (Structural)

LOW SEISMICITY						
BUILDING SYSTEMS - GENERAL						
		Description				
C	NC	N/A	U	LOAD PATH: The structure contains a complete, well-defined load path, including structural elements and connections, that serves to transfer the inertial forces associated with the mass of all elements of the building to the foundation. (Commentary: Sec. A.2.1.1. Tier 2: Sec. 5.4.1.1)		
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Comments: 5/8" plywood roof diaphragms deliver loads to wood shear walls over strip footings in transverse direction and to wood diagonal braces and wood columns over spread footings.		
C	NC	N/A	U	ADJACENT BUILDINGS: The clear distance between the building being evaluated and any adjacent building is greater than 0.25% of the height of the shorter building in low seismicity, 0.5% in moderate seismicity, and 1.5% in high seismicity. (Commentary: Sec. A.2.1.2. Tier 2: Sec. 5.4.1.2)		
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Comments: The canopy over the walkway connects Building G to Building F. There are no seismic separations or collectors on either side. To the east of the canopy, a portion of Building G also connects to Building F. There are no collectors linking Building F and G.		
C	NC	N/A	U	MEZZANINES: Interior mezzanine levels are braced independently from the main structure or are anchored to the seismic-force-resisting elements of the main structure. (Commentary: Sec. A.2.1.3. Tier 2: Sec. 5.4.1.3)		
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Comments: There are some light storage mezzanines that are not seismically braced.		
BUILDING SYSTEMS - BUILDING CONFIGURATION						
		Description				
C	NC	N/A	U	WEAK STORY: The sum of the shear strengths of the seismic-force-resisting system in any story in each direction is not less than 80% of the strength in the adjacent story above. (Commentary: Sec. A.2.2.2. Tier 2: Sec. 5.4.2.1)		
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Comments: Single story structure.		
C	NC	N/A	U	SOFT STORY: The stiffness of the seismic-force-resisting system in any story is not less than 70% of the seismic-force-resisting system stiffness in an adjacent story above or less than 80% of the average seismic-force-resisting system stiffness of the three stories above. (Commentary: Sec. A.2.2.3. Tier 2: Sec. 5.4.2.2)		
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Comments: Single story structure.		
C	NC	N/A	U	VERTICAL IRREGULARITIES: All vertical elements in the seismic-force-resisting system are continuous to the foundation. (Commentary: Sec. A.2.2.4. Tier 2: Sec. 5.4.2.3)		
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Comments: All lateral force-resisting system elements are continuous to the foundation.		

UC Campus:	Santa Cruz		Date:	06/28/2019		
Building CAAN:	7499	Auxiliary CAAN:	By Firm:	Rutherford + Chekene		
Building Name:	Elena Baskin Visual Arts Building G		Initials:	JY	Checked:	WAL/BL
Building Address:	Santa Cruz, CA 95064		Page:	1	of	3

ASCE 41-17 Collapse Prevention Basic Configuration

C NC N/A U <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<p>GEOMETRY: There are no changes in the net horizontal dimension of the seismic-force-resisting system of more than 30% in a story relative to adjacent stories, excluding one-story penthouses and mezzanines. (Commentary: Sec. A.2.2.5. Tier 2: Sec. 5.4.2.4)</p> <p>Comments: Single story structure.</p>
C NC N/A U <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<p>MASS: There is no change in effective mass of more than 50% from one story to the next. Light roofs, penthouses, and mezzanines need not be considered. (Commentary: Sec. A.2.2.6. Tier 2: Sec. 5.4.2.5)</p> <p>Comments: Single story structure.</p>
C NC N/A U <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<p>TORSION: The estimated distance between the story center of mass and the story center of rigidity is less than 20% of the building width in either plan dimension. (Commentary: Sec. A.2.2.7. Tier 2: Sec. 5.4.2.6)</p> <p>Comments: Flexible diaphragm</p>

MODERATE SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR LOW SEISMICITY)

GEOLOGIC SITE HAZARD

	Description
C NC N/A U <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<p>LIQUEFACTION: Liquefaction-susceptible, saturated, loose granular soils that could jeopardize the building's seismic performance do not exist in the foundation soils at depths within 50 ft (15.2m) under the building. (Commentary: Sec. A.6.1.1. Tier 2: 5.4.3.1)</p> <p>Comments: Per 2009 County map at https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LiquifactionMap2009.pdf</p>
C NC N/A U <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<p>SLOPE FAILURE: The building site is located away from potential earthquake-induced slope failures or rockfalls so that it is unaffected by such failures or is capable of accommodating any predicted movements without failure. (Commentary: Sec. A.6.1.2. Tier 2: 5.4.3.1)</p> <p>Comments: Per 2009 County map at https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LandslideMap2009.pdf</p>
C NC N/A U <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<p>SURFACE FAULT RUPTURE: Surface fault rupture and surface displacement at the building site are not anticipated. (Commentary: Sec. A.6.1.3. Tier 2: 5.4.3.1)</p> <p>Comments: Per 2009 County map at https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/FaultZoneMap2009.pdf</p>

UC Campus:	Santa Cruz		Date:	06/28/2019	
Building CAAN:	7499	Auxiliary CAAN:	By Firm:	Rutherford + Chekene	
Building Name:	Elena Baskin Visual Arts Building G		Initials:	JY	Checked: WAL/BL
Building Address:	Santa Cruz, CA 95064		Page:	1	of 3

ASCE 41-17 Collapse Prevention Basic Configuration

HIGH SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR MODERATE SEISMICITY)

FOUNDATION CONFIGURATION

	Description
C NC N/A U <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<p>OVERTURNING: The ratio of the least horizontal dimension of the seismic-force-resisting system at the foundation level to the building height (base/height) is greater than $0.6S_a$. (Commentary: Sec. A.6.2.1. Tier 2: Sec. 5.4.3.3)</p> <p>Comments: Building width $B = 40'$, Building Height is $H = 14'$, $B/H = 2.86$ $S_a = 1.28g$ per ATC at BSE-2E $0.6 \times S_a = 0.77$ $B/H > 0.6 S_a$</p>
C NC N/A U <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<p>TIES BETWEEN FOUNDATION ELEMENTS: The foundation has ties adequate to resist seismic forces where footings, piles, and piers are not restrained by beams, slabs, or soils classified as Site Class A, B, or C. (Commentary: Sec. A.6.2.2. Tier 2: Sec. 5.4.3.4)</p> <p>Comments: Concrete on grade ties to the perimeter foundations.</p>

UC Campus:	Santa Cruz			Date:	06/28/2019		
Building CAAN:	7499	Auxiliary CAAN:		By Firm:	Rutherford + Chekene		
Building Name:	Elena Baskin Visual Arts Building G			Initials:	JY	Checked:	WAL/BL
Building Address:	Santa Cruz, CA 95064			Page:	1	of	4

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type W2

LOW AND MODERATE SEISMICITY															
SEISMIC-FORCE-RESISTING SYSTEM															
				Description											
C	NC	N/A	U	REDUNDANCY: The number of lines of shear walls in each principal direction is greater than or equal to 2. (Commentary: Sec. A.3.2.1.1. Tier 2: Sec. 5.5.1.1)											
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Comments:											
C	NC	N/A	U	SHEAR STRESS CHECK: The shear stress in the shear walls, calculated using the Quick Check procedure of Section 4.4.3.3, is less than the following values: (Commentary: Sec. A.3.2.7.1. Tier 2: Sec. 5.5.3.1.1)											
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Structural panel sheathing</td> <td>1,000 lb/ft</td> </tr> <tr> <td>Diagonal sheathing</td> <td>700 lb/ft</td> </tr> <tr> <td>Straight sheathing</td> <td>100 lb/ft</td> </tr> <tr> <td>All other conditions</td> <td>100 lb/ft</td> </tr> </table>				Structural panel sheathing	1,000 lb/ft	Diagonal sheathing	700 lb/ft	Straight sheathing	100 lb/ft	All other conditions	100 lb/ft
Structural panel sheathing	1,000 lb/ft														
Diagonal sheathing	700 lb/ft														
Straight sheathing	100 lb/ft														
All other conditions	100 lb/ft														
C	NC	N/A	U	STUCCO (EXTERIOR PLASTER) SHEAR WALLS: Multi-story buildings do not rely on exterior stucco walls as the primary seismic-force-resisting system. (Commentary: Sec. A.3.2.7.2. Tier 2: Sec. 5.5.3.6.1)											
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Comments: Single story building, and plywood and wood braced frames are used to resist lateral forces.											
C	NC	N/A	U	GYPSUM WALLBOARD OR PLASTER SHEAR WALLS: Interior plaster or gypsum wallboard is not used for shear walls on buildings more than one story high with the exception of the uppermost level of a multi-story building. (Commentary: Sec. A.3.2.7.3. Tier 2: Sec. 5.5.3.6.1)											
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Comments: Plywood and wood braced frames are used to resist lateral forces.											
C	NC	N/A	U	NARROW WOOD SHEAR WALLS: Narrow wood shear walls with an aspect ratio greater than 2-to-1 are not used to resist seismic forces. (Commentary: Sec. A.3.2.7.4. Tier 2: Sec. 5.5.3.6.1)											
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Comments: Piers typically have aspect ratios of less than 2V:1H.											
C	NC	N/A	U	WALLS CONNECTED THROUGH FLOORS: Shear walls have an interconnection between stories to transfer overturning and shear forces through the floor. (Commentary: Sec. A.3.2.7.5. Tier 2: Sec. 5.5.3.6.2)											
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Comments: Single story structure.											

UC Campus:	Santa Cruz		Date:	06/28/2019	
Building CAAN:	7499	Auxiliary CAAN:	By Firm:	Rutherford + Chekene	
Building Name:	Elena Baskin Visual Arts Building G		Initials:	JY	Checked: WAL/BL
Building Address:	Santa Cruz, CA 95064		Page:	3	of 4

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type W2

C <input checked="" type="checkbox"/> NC <input type="checkbox"/> N/A <input type="checkbox"/> U <input type="checkbox"/>	HILLSIDE SITE: For structures that are taller on at least one side by more than one-half story because of a sloping site, all shear walls on the downhill slope have an aspect ratio less than 1-to-1. (Commentary: Sec. A.3.2.7.6. Tier 2: Sec. 5.5.3.6.3)
	Comments: No sloping site.
C <input checked="" type="checkbox"/> NC <input type="checkbox"/> N/A <input type="checkbox"/> U <input type="checkbox"/>	CRIPPLE WALLS: Cripple walls below first-floor-level shear walls are braced to the foundation with wood structural panels. (Commentary: Sec. A.3.2.7.7. Tier 2: Sec. 5.5.3.6.4)
	Comments: No cripple walls.
C <input checked="" type="checkbox"/> NC <input type="checkbox"/> N/A <input type="checkbox"/> U <input type="checkbox"/>	OPENINGS: Walls with openings greater than 80% of the length are braced with wood structural panel shear walls with aspect ratios of not more than 1.5-to-1 or are supported by adjacent construction through positive ties capable of transferring the seismic forces. (Commentary: Sec. A.3.2.7.8. Tier 2: Sec. 5.5.3.6.5)
	Comments: No large openings observed in wood shear walls.
CONNECTIONS	
	Description
C <input checked="" type="checkbox"/> NC <input type="checkbox"/> N/A <input type="checkbox"/> U <input type="checkbox"/>	WOOD POSTS: There is a positive connection of wood posts to the foundation. (Commentary: Sec. A.5.3.3. Tier 2: Sec. 5.7.3.3)
	Comments: Simpson CB-68 or CB-88 connections are used for column base connection to concrete foundation per Detail 12 on Sheet S-7.
C <input checked="" type="checkbox"/> NC <input type="checkbox"/> N/A <input type="checkbox"/> U <input type="checkbox"/>	WOOD SILLS: All wood sills are bolted to the foundation. (Commentary: Sec. A.5.3.4. Tier 2: Sec. 5.7.3.3)
	Comments: Wood sills are bolted 5/8" dia. anchor bolts on 4'-0" o.c. per Detail 16 on Sheet S-7.
C <input checked="" type="checkbox"/> NC <input type="checkbox"/> N/A <input type="checkbox"/> U <input type="checkbox"/>	GIRDER/COLUMN CONNECTION: There is a positive connection using plates, connection hardware, or straps between the girder and the column support. (Commentary: Sec. A.5.4.1. Tier 2: Sec. 5.7.4.1)
	Comments: Structural steel angle w/ 3/4" dia. through bolts are used to connect girder and column per Detail 2 and 7 on Sheet S-7

UC Campus:	Santa Cruz		Date:	06/28/2019	
Building CAAN:	7499	Auxiliary CAAN:	By Firm:	Rutherford + Chekene	
Building Name:	Elena Baskin Visual Arts Building G		Initials:	JY	Checked: WAL/BL
Building Address:	Santa Cruz, CA 95064		Page:	3	of 4

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type W2

HIGH SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR LOW AND MODERATE SEISMICITY)

CONNECTIONS

	Description								
<table border="0"> <tr> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>C</td> <td>NC</td> <td>N/A</td> <td>U</td> </tr> </table>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	C	NC	N/A	U	<p>WOOD SILL BOLTS: Sill bolts are spaced at 6 ft (1.8 m) or less with acceptable edge and end distance provided for wood and concrete. (Commentary: A.5.3.7. Tier 2: Sec. 5.7.3.3)</p> <p>Comments: Wood sills are bolted 5/8" dia. anchor bolts on 4'-0" o.c. per Detail 16 on Sheet S-7</p>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>						
C	NC	N/A	U						

DIAPHRAGMS

	Description								
<table border="0"> <tr> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>C</td> <td>NC</td> <td>N/A</td> <td>U</td> </tr> </table>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	C	NC	N/A	U	<p>DIAPHRAGM CONTINUITY: The diaphragms are not composed of split-level floors and do not have expansion joints. (Commentary: Sec. A.4.1.1. Tier 2: Sec. 5.6.1.1)</p> <p>Comments: Single story structure.</p>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>						
C	NC	N/A	U						
<table border="0"> <tr> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>C</td> <td>NC</td> <td>N/A</td> <td>U</td> </tr> </table>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	C	NC	N/A	U	<p>ROOF CHORD CONTINUITY: All chord elements are continuous, regardless of changes in roof elevation. (Commentary: Sec. A.4.1.3. Tier 2: Sec. 5.6.1.1)</p> <p>Comments: Chord discontinuity occur at each roof offset locations.</p>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>						
C	NC	N/A	U						
<table border="0"> <tr> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>C</td> <td>NC</td> <td>N/A</td> <td>U</td> </tr> </table>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	C	NC	N/A	U	<p>DIAPHRAGM REINFORCEMENT AT OPENINGS: There is reinforcing around all diaphragm openings larger than 50% of the building width in either major plan dimension. (Commentary: Sec. A.4.1.8. Tier 2: Sec. 5.6.1.5)</p> <p>Comments: No large opening observed in the roof diaphragm.</p>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>						
C	NC	N/A	U						
<table border="0"> <tr> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>C</td> <td>NC</td> <td>N/A</td> <td>U</td> </tr> </table>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	C	NC	N/A	U	<p>STRAIGHT SHEATHING: All straight-sheathed diaphragms have aspect ratios less than 2-to-1 in the direction being considered. (Commentary: Sec. A.4.2.1. Tier 2: Sec. 5.6.2)</p> <p>Comments: Roof is sheathed with plywood.</p>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>						
C	NC	N/A	U						
<table border="0"> <tr> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>C</td> <td>NC</td> <td>N/A</td> <td>U</td> </tr> </table>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	C	NC	N/A	U	<p>SPANS: All wood diaphragms with spans greater than 24 ft (7.3 m) consist of wood structural panels or diagonal sheathing. (Commentary: Sec. A.4.2.2. Tier 2: Sec. 5.6.2)</p> <p>Comments: 5/8" plywood per Detail 12 on Sheet S-1</p>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>						
C	NC	N/A	U						

UC Campus:	Santa Cruz		Date:	06/28/2019	
Building CAAN:	7499	Auxiliary CAAN:	By Firm:	Rutherford + Chekene	
Building Name:	Elena Baskin Visual Arts Building G		Initials:	JY	Checked: WAL/BL
Building Address:	Santa Cruz, CA 95064		Page:	3	of 4

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type W2

C <input type="checkbox"/> NC <input type="checkbox"/> N/A <input checked="" type="checkbox"/> U <input type="checkbox"/>		DIAGONALLY SHEATHED AND UNBLOCKED DIAPHRAGMS: All diagonally sheathed or unblocked wood structural panel diaphragms have horizontal spans less than 40 ft (12.2 m) and have aspect ratios less than or equal to 4-to-1. (Commentary: Sec. A.4.2.3. Tier 2: Sec. 5.6.2)
		Comments: 5/8" plywood
C <input type="checkbox"/> NC <input type="checkbox"/> N/A <input checked="" type="checkbox"/> U <input type="checkbox"/>		OTHER DIAPHRAGMS: The diaphragms do not consist of a system other than wood, metal deck, concrete, or horizontal bracing. (Commentary: Sec. A.4.7.1. Tier 2: Sec. 5.6.5)
		Comments: 5/8" plywood



Rating form
completed by:

RUTHERFORD + CHEKENE
ruthchek.com

Evaluator: JY/WAL/BL

Date: 06/28/2019

APPENDIX C

UCOP Seismic Safety Policy Falling Hazards Assessment Summary

UC Campus:	Santa Cruz		Date:	06/28/2019	
Building CAAN:	7499	Auxiliary CAAN:	By Firm:	Rutherford + Chekene	
Building Name:	EBASK BLDG G		Initials:	JY	Checked: WAL/BL
Building Address:	Santa Cruz, CA 95064		Page:		of

UCOP SEISMIC SAFETY POLICY Falling Hazard Assessment Summary

		Description
P <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>	Heavy ceilings, features or ornamentation above large lecture halls, auditoriums, lobbies, or other areas where large numbers of people congregate (50 ppl or more) Comments:
P <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>	Heavy masonry or stone veneer above exit ways or public access areas Comments:
P <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>	Unbraced masonry parapets, cornices, or other ornamentation above exit ways or public access areas Comments:
P <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>	Unrestrained hazardous material storage Comments:
P <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>	Masonry chimneys Comments:
P <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>	Unrestrained natural gas-fueled equipment such as water heaters, boilers, emergency generators, etc. Comments:
P <input checked="" type="checkbox"/>	N/A <input type="checkbox"/>	Other: Lockers in corridor and in rooms Comments: Lockers are not properly anchored.
P <input checked="" type="checkbox"/>	N/A <input type="checkbox"/>	Other: Storage mezzanine Comments: Items on the mezzanine are falling hazards during an earthquake event.
P <input type="checkbox"/>	N/A <input type="checkbox"/>	Other: Comments:

Falling Hazards Risk: **Low**



Rating form
completed by:

RUTHERFORD + CHEKENE

ruthchek.com

Evaluator: JY/WAL/BL

Date: 06/28/2019

APPENDIX D

Quick Check Calculations

Unit Weights:

	Seismic Weight	Dead Load	
Main BLDG Roof	psf		Remarks
roofing	3	3	Metal roof per arch dwg; Product specification not available
5/8" plywood	1.5	1.5	at 36 pcf
rafter	4	4	2x10 @ 16" o.c.
MEP	3	6	
ceiling	2	2	typ. gypboard ceiling panels
misc+lighting	5	5	
partition including shear walls	7.5		half of 15 psf
Total	26	21	

	Seismic Weight	Dead Load	
Canopy Roof	psf		Remarks
roofing	3	3	Metal roof per arch dwg; Product specification not available
5/8" plywood	1.5	1.5	at 36 pcf
rafter	3	3	2x8 @ 24" o.c.
misc.+lighting	2	2	
Total	10	8	

	Seismic Weight	Dead Load	
Storage Mezzanine	psf		Remarks
3/4" plywood	2	2	at 33 pcf
joists	3.5	3.5	2x10 @16
misc+lighting	6	6	
Storage	35	35	Assumed weight
Total	47	47	

	Seismic Weight	Dead Load	
Print Studio	psf		Remarks
roofing	3	3	asphalt shingles and felt underlayment
5/8" plywood	1.5	1.5	at 33 pcf
rafter	2	2	2x10 @ 16" o.c.
MEP+misc+lighting	15	15	
ceiling	2	2	
partition including shear walls	10		account for more than typ. # of partitions observed during site visit
Total	34	24	

Story Weights

Level	Area (ft ²)	Unit Weight (psf)	Seismic Weight (kips)
Typ. Roof	1775	26	45
Storage Mezz	140	47	7
Canopy Roof	1061	10	10
Print Studio	2650	34	89
			151

Period

C_t =	0.02
h_n (ft)=	14
B =	0.75

T =	0.14	sec
-------	------	-----

BSE-2E Response Spectrum

Latitude, Longitude: 36.994539, -122.061018



Date	6/28/2019, 10:12:27 AM
Design Code Reference Document	ASCE41-17
Custom Probability	
Site Class	D - Stiff Soil

Type	Description	Value
Hazard Level		BSE-2E
S_S	spectral response (0.2 s)	1.281
S_1	spectral response (1.0 s)	0.485
S_{XS}	site-modified spectral response (0.2 s)	1.281
S_{X1}	site-modified spectral response (1.0 s)	0.88
f_a	site amplification factor (0.2 s)	1
f_v	site amplification factor (1.0 s)	1.815

Story Shears

Sa=	1.28
W=	151 kips
C=	1.3 from Table 4-7

V=	251 kips
----	----------

k= 1.00

Story Shears	height	total height	Weight	weight*height^k	coeff	Fx	Story Shear
Floor Levels							
Roof	14.33	14.3	151	2159	1.00	251	251
				2159		251	

Average Stress:

Ms=	4.5	CP of wood shear wall
-----	-----	-----------------------

N-S direction (Transverse)			
Level	Force (kips)	length of wall (ft)	average shear stress (plf)
Roof	251	100	557