

Rating form  
completed by:**RUTHERFORD + CHEKENE**  
ruthchek.com

Evaluator: MTN/EFA/BL

Date: 06/28/2019

Text in *green* is to be part of UC Santa Cruz building database and may be part of UCOP database

DATE: 2019-06-28

## UC Santa Cruz building seismic ratings

### Elena Baskin Visual Arts Building J (Painting Studio)

CAAN #7822

Elena Baskin Visual Arts, Santa Cruz, CA 95064

UCSC Campus: **Main Campus**

Northeast Corner (Looking Southwest)

Plan



| Rating summary   | Entry                | Notes   |
|--|----------------------|---|
| UC Seismic Performance Level (rating)                                  | V (Poor)             |   |
| Rating basis   | Tier 1               | ASCE 41-17 <sup>1</sup>   |
| Date of rating   | 2019                 |   |
| Recommended list assignment (UC Santa Cruz category for retrofit)      | Priority B           | Priority A =Retrofit ASAP<br>Priority B=Retrofit at next permit application         |
| Ballpark total construction cost to retrofit to IV rating <sup>2</sup> | Medium (\$50-200/sf) | See recommendations on further evaluation and retrofit.                             |
| Is 2018-2019 rating required by UCOP?                                  | Yes                  | Building was not previously rated.  |
| Further evaluation recommended?  | Yes                  | To quantify the demands and capacities along the entire unusual roof diaphragm path |

<sup>1</sup> We translate this Tier 1 evaluation to a Seismic Performance Level rating using professional judgment. Non-compliant items in the Tier 1 evaluation do not automatically put a building into a particular rating category, but we evaluate such items along with the combination of building features and potential deficiencies, focused on the potential for collapse or serious damage to the gravity supporting structure that may threaten occupant safety. See Section III.B of the 19 May 2017 *UC Seismic Safety Policy* and Method B of Section 321 of the 2016 *California Building Code*.

<sup>2</sup> Per Section III.A.4.i of the 26 March 2019 *UC Seismic Program Guidebook, Version 1.3*, the cost includes all construction cost necessitated by the seismic retrofit, including restoration of finishes and any triggered work on utilities or accessibility. It does not include soft costs such as design fees or campus costs. The cost is in 2019 dollars

**Building information used in this evaluation**

- Architectural drawings by Paulett Taggart Architects, "Painting Studio, Baskin Visual Arts Complex, University of California, Santa Cruz," dated 10 November 1992.
- Structural drawings by Lawrence Fowler and Associates, "Painting Studio, Baskin Visual Arts Complex, University of California, Santa Cruz," signed 31 December 1993.

**Additional building information known to exist**

None

**Scope for completing this form**

Reviewed structural drawings for original construction, made a brief site visit was performed on 23 May 2019, and carried out ASCE 41-17 Tier 1 evaluation.

**Brief description of structure**

The Painting Studio Building was designed in 1992 by Paulett Taggart Architects; Lawrence Fowler and Associates was the structural engineer. Construction was completed in 1993.

The plan is rectangular with east-west dimension of 51'-4 1/2" and north-south dimension of 41'-1". There is a triangularly-shaped canopy on the north side with a north-south dimension of 9'-11 3/4" and an east-west direction 16'-9 3/4". The site slopes down slightly from north to south and from west to east. The soil is retained with concrete retaining walls on the north and west side of the building.

Building condition: in general, the building is in good structural condition. No significant damage in the structural system was observed during the site visit.

Identification of levels: One story.

Foundation System: The superstructure is founded on shallow strip footings located under plywood shear walls and concrete retaining walls on the north and west side of the building. The ground floor consists of a 4" thick reinforced concrete slab-on-grade.

Structural system for vertical (gravity) load: The roof is sawtooth in shape, framed with typical 2x6 at 24" o.c. rafters and 3/4" plywood sheathing board with 8d at 3" o.c. at panel edges and 12" o.c. in field with all edges blocked. The top end of the rafters is supported by a 4x10 header spanning between 4x4 wood posts. The posts are supported by a 6-3/4"x27" glulam beam which also supports the bottom end of the rafters. There are six glulams which span diagonally in the NW-SE direction and bear at their ends on 6x6 wood posts integrated into the perimeter stud walls. The perimeter wood-framed walls are anchored to the strip footings and concrete retaining walls on the north and west side of the building.

Structural system for lateral forces: In both directions, the vertical elements of the lateral load-resisting system consist of plywood shear walls with 2x6 (at exterior walls) and 2x4 (at interior walls) studs at 16" o.c. The walls are sheathed with 1/2" plywood with typical 8d nails at 6" o.c. at edges and 12" o.c. in the field. The in-plane load transfer between the roof diaphragm to the plywood shear walls consists of edge nailing. The plywood shear walls are anchored to the concrete slab or concrete retaining wall with 5/8" diameter anchor bolts at 32" o.c.

The key architectural feature of the building are the sawtooth roofs which create large clerestory windows and interrupt the roof diaphragm and are oriented diagonally in plan with the perimeter walls. The structural approach taken to address this is unusual.

Lateral loads in the NE-SW direction will span through each monoslope plywood diaphragm roof segment to its ends on the NW and SE sides where the perimeter plywood walls are located. The aspect ratio of the roof segments is poor (ranging from about 3:1 to 6.5:1), but there are a set of struts parallel to the rafters (running NE-SW) made of a 4x6 in the plane of the sloped roof and a TS3x2x3/16 at the glulam level which will help link each roof segment together. The struts do not always align on each side of the glulam so the glulam will act in weak way bending.

Lateral loads in the NW-SW direction have a series of nominally connected roof segments because of the clerestory window. At each end of the glulam, there is a ½" diameter tie rod in Detail 8/S4 which vertically connects the 4x10 header at the top of the clerestory window down to the glulam at the bottom of the window. Internal load transfer within the diaphragm through the tie rods will be small, but the tie rods are also relatively small. The combined plywood and tie-rod bracing diaphragm connects to the perimeter walls and transfers loads into the walls and down to the foundation.

### Brief description of seismic deficiencies and expected seismic performance including mechanism of nonlinear response and structural behavior modes

Identified seismic features and deficiencies of the building include the following:

- The only deficiency is that of the roof diaphragm discontinuity created by the sawtooth roof segments. In the NE-SW direction, this creates high diaphragm aspect ratios. In the NW-SE direction, the unusual combination of plywood and tension rods in the windows limits diaphragm capacity in the load path and increases diaphragm flexibility.

| Structural deficiency   | Affects rating? | Structural deficiency                                    | Affects rating? |
|---|-----------------|--|-----------------|
| Lateral system stress check (wall shear, column shear or flexure, or brace axial as applicable) | N               | Openings at shear walls (concrete or masonry)            | N               |
| Load path   | N               | Liquefaction   | N               |
| Adjacent buildings  | N               | Slope failure  | N               |
| Weak story  | N               | Surface fault rupture                                    | N               |
| Soft story  | N               | Masonry or concrete wall anchorage at flexible diaphragm | N               |
| Geometry (vertical irregularities)  | N               | URM wall height-to-thickness ratio                       | N               |
| Torsion   | N               | URM parapets or cornices                                 | N               |
| Mass – vertical irregularity  | N               | URM chimney  | N               |
| Cripple walls   | N               | Heavy partitions braced by ceilings                      | N               |
| Wood sills (bolting)  | N               | Appendages   | N               |
| Diaphragm continuity  | Y               |  |                 |

### Summary of review of nonstructural life-safety concerns, including at exit routes.<sup>3</sup>

No significant nonstructural life-safety concerns were observed during our site visit.

| UCOP nonstructural checklist item  | Life safety hazard? | UCOP nonstructural checklist item  | Life safety hazard? |
|--|---------------------|--|---------------------|
| Heavy ceilings, feature or ornamentation above large lecture halls, auditoriums, lobbies or other areas where large numbers of people congregate | None observed       | Unrestrained hazardous materials storage   | None observed       |
| Heavy masonry or stone veneer above exit ways and public access areas  | None observed       | Masonry chimneys   | None observed       |
| Unbraced masonry parapets, cornices or other ornamentation above exit ways and public access areas   | None observed       | Unrestrained natural gas-fueled equipment such as water heaters, boilers, emergency generators, etc. | None observed       |

### Basis of rating

We assign a Seismic Performance Level rating of V to this building. The walls have relatively low demands, but the sawtooth roof diaphragm has limited capacity to adequately resist loads, particularly in the NW-SE direction. A more

<sup>3</sup> For these Tier 1 evaluations, we do not visit all spaces of the building; we rely on campus staff to report to us their understanding of if and where nonstructural hazards may occur.

detailed analysis beyond the scope of the Tier 1 evaluation is needed to evaluate the adequacy of the system, including the tie rods, their connections, and the struts

### Recommendations for further evaluation or retrofit

We recommend that at Tier 2 evaluation be performed to investigate in detail the adequacy of the segmented roof diaphragm including the tie rods, their connections, the struts, and weak way bending of the wood members. If these are found to be adequate, this could lead to an improvement in the rating from level V to Level IV.

### None. Comments on rating

The key issues with the sawtooth roof and the adequacy of the diaphragm are similar to issues with the Baskin Buildings E, F, and G (CAAN #7497, #7498, and #7499) which also have sawtooth roofs, but use a heavy timber brace to connect the high and low roofs at the clerestory windows. The peer review of those buildings, carried out on 28 May 2019, confirmed a Level V rating and recommendation for a Tier 2 evaluation, and can be extended to this Building J. Reviewers present were Joe Maffei of Maffei Structural Engineering and Holly Razzano and Jay Yin of Degenkolb Engineers.

| Additional building data   | Entry                | Notes  |
|--|----------------------|--|
| Latitude   | 36.994360            |  |
| Longitude  | -122.060200          |  |
| Are there other structures besides this one under the same CAAN# | No                   |  |
| Number of stories above lowest perimeter grade                   | 1                    |  |
| Number of stories (basements) below lowest perimeter grade       | 0                    |  |
| Building occupiable area (OGSF)                                  | 2,201                |  |
| Risk Category per 2016 CBC Table 1604.5                          | II                   |  |
| Building structural height, $h_n$                                | 16 ft                | Structural height defined per ASCE 7-16 Section 11.2 |
| Coefficient for period, $C_t$                                    | 0.020                | Estimated using ASCE 41-17 equation 4-4 and 7-18     |
| Coefficient for period, $\beta$                                  | 0.75                 | Estimated using ASCE 41-17 equation 4-4 and 7-18     |
| Estimated fundamental period                                     | 0.16 sec             | Estimated using ASCE 41-17 equation 4-4 and 7-18     |
| Site data  |                      |  |
| 975-year hazard parameters $S_s, S_1$                            | 1.281, 0.485         | From OSHPD/SEAOC website                             |
| Site class   | D                    |  |
| Site class basis   | Geotech <sup>4</sup> | See footnote below                                   |
| Site parameters $F_a, F_v$                                       | 1.0, 1.815           | From OSHPD/SEAOC website                             |

<sup>4</sup> Determination of site class and assessment of geotechnical hazards are based on correspondence with Pacific Crest Geotechnical Engineers and Nolan, Zinn, and Associates Geologists. [Revised Geology and Geologic Hazards, Santa Cruz Campus, University of California, Job # 04003-SC 13 May 2005]. Site class is taken as D throughout the main campus of UC Santa Cruz. The following links provide hazard maps for liquefaction, landslide, and fault rupture:

<https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LiquifactionMap2009.pdf>

<https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LandslideMap2009.pdf>

<https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/FaultZoneMap2009.pdf>

|  |                               |   |
|--|-------------------------------|---|
| Ground motion parameters $S_{cs}$ , $S_{c1}$             | 1.281, 0.881                  | From OSHPD/SEAOC website  |
| $S_a$ at building period                                 | 1.28                          |   |
| Site $V_{s30}$   | 900 ft/s                      |   |
| $V_{s30}$ basis  | Estimated                     | Estimated based on site classification of D.                      |
| Liquefaction potential                                   | Low                           |   |
| Liquefaction assessment basis                            | County map                    | See footnote below  |
| Landslide potential                                      | Low                           |   |
| Landslide assessment basis                               | County map                    | See footnote below  |
| Active fault rupture identified at site                  | No                            |   |
| Fault rupture assessment basis                           | County map                    | See footnote below  |
| Site-specific ground motion study?                       | No                            |   |
| <b>Applicable code</b>                                   |                               |   |
| Applicable code or approx. date of original construction | Built: 1993<br>Code: UBC 1988 | Per drawings, Sheet A 1   |
| Applicable code for partial retrofit                     | None                          | No partial retrofit   |
| Applicable code for full retrofit                        | None                          | No full retrofit  |
| <b>FEMA P-154 data</b>                                   |                               |   |
| Model building type North-South                          | W2-Wood<br>Frames             |   |
| Model building type East-West                            | W2-Wood<br>Frames             |   |
| FEMA P-154 score   | N/A                           | Not included here because we performed ASCE 41 Tier 1 evaluation. |
| <b>Previous ratings</b>                                  |                               |   |
| Most recent rating                                       | -                             | Building was not previously rated.                                |
| Date of most recent rating                               | -                             |   |
| 2 <sup>nd</sup> most recent rating                       | -                             |   |
| Date of 2 <sup>nd</sup> most recent rating               | -                             |   |
| 3 <sup>rd</sup> most recent rating                       | -                             |   |
| Date of 3 <sup>rd</sup> most recent rating               | -                             |   |
| <b>Appendices</b>  |                               |   |
| ASCE 41 Tier 1 checklist included here?                  | Yes                           | Refer to attached checklist file                                  |




Rating form  
completed by:

Evaluator: MTN/EFA/BL


Date: 06/20/2019

**Color Coded Floor Plan:**




**Roof**

### Slab on grade and shear wall location




### Roof framing and description of typical sawtooth segment








Typical roof details



Details for the roof struts and tie rods



Architectural cross section





---

## **APPENDIX A**

### **Additional Photos**



Northeast corner (looking southwest)



Northwest corner (looking southeast)



Southeast corner (looking northwest)



Southwest corner (looking northeast)



Glulam beams supporting clerestory windows.

Note the tie rod in the upper left corner running from the bottom of 4x10 header over the windows to the top of the 6-3/4" x 27" glulam at the bottom chord. The TX3x2x3/16 struts are also visible at the bottom chord level.



---

## **APPENDIX B**

### **ASCE 41-17 Tier 1 Checklists (Structural)**



|                   |                                     |                 |           |                      |          |        |
|-------------------|-------------------------------------|-----------------|-----------|----------------------|----------|--------|
| UC Campus:        | Santa Cruz                          |                 | Date:     | 06/28/2019           |          |        |
| Building CAAN:    | 7822                                | Auxiliary CAAN: | By Firm:  | RUTHERFORD + CHEKENE |          |        |
| Building Name:    | Elena Baskin Visual Arts Building J |                 | Initials: | MN                   | Checked: | WAL/BL |
| Building Address: | Santa Cruz, CA 95064                |                 | Page:     | 1                    | of       | 3      |

## ASCE 41-17 Collapse Prevention Basic Configuration Checklist

### LOW SEISMICITY

#### BUILDING SYSTEMS - GENERAL

|   | Description   |
|---|---|
| <b>C NC N/A U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p><b>LOAD PATH:</b> The structure contains a complete, well-defined load path, including structural elements and connections, that serves to transfer the inertial forces associated with the mass of all elements of the building to the foundation. (Commentary: Sec. A.2.1.1. Tier 2: Sec. 5.4.1.1)</p> <p><b>Comments:</b> Wood-framed roof diaphragm with 3/4" plywood sheathing deliver loads to wood-frame walls and wood columns over strip footing in both directions. Transfer within the roof diaphragm include steel tie rods at the sawtooth segments from the members above and below the windows.</p> |
| <b>C NC N/A U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p><b>ADJACENT BUILDINGS:</b> The clear distance between the building being evaluated and any adjacent building is greater than 0.25% of the height of the shorter building in low seismicity, 0.5% in moderate seismicity, and 1.5% in high seismicity. (Commentary: Sec. A.2.1.2. Tier 2: Sec. 5.4.1.2)</p> <p><b>Comments:</b><br/>Clear distance between the building being evaluated and adjacent building, <math>d = 7'</math> (approx.)<br/>height of the shorter building, <math>h = 14'</math> (approx.)<br/><math>d &gt; 0.015 * h = 0.21'</math></p>   |
| <b>C NC N/A U</b><br><input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> | <p><b>MEZZANINES:</b> Interior mezzanine levels are braced independently from the main structure or are anchored to the seismic-force-resisting elements of the main structure. (Commentary: Sec. A.2.1.3. Tier 2: Sec. 5.4.1.3)</p> <p><b>Comments:</b> There are no mezzanines.</p>   |

#### BUILDING SYSTEMS - BUILDING CONFIGURATION

|   | Description  |
|---|--|
| <b>C NC N/A U</b><br><input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> | <p><b>WEAK STORY:</b> The sum of the shear strengths of the seismic-force-resisting system in any story in each direction is not less than 80% of the strength in the adjacent story above. (Commentary: Sec. A.2.2.2. Tier 2: Sec. 5.4.2.1)</p> <p><b>Comments:</b> Single story structure.</p>   |
| <b>C NC N/A U</b><br><input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> | <p><b>SOFT STORY:</b> The stiffness of the seismic-force-resisting system in any story is not less than 70% of the seismic-force-resisting system stiffness in an adjacent story above or less than 80% of the average seismic-force-resisting system stiffness of the three stories above. (Commentary: Sec. A.2.2.3. Tier 2: Sec. 5.4.2.2)</p> <p><b>Comments:</b> Single story structure.</p> |
| <b>C NC N/A U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p><b>VERTICAL IRREGULARITIES:</b> All vertical elements in the seismic-force-resisting system are continuous to the foundation. (Commentary: Sec. A.2.2.4. Tier 2: Sec. 5.4.2.3)</p> <p><b>Comments:</b> All vertical elements in the seismic-force-resisting system are continuous to the foundation.</p>  |

**Note:** C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

|                   |  |                 |           |                             |          |               |
|-------------------|--|-----------------|-----------|-----------------------------|----------|---------------|
| UC Campus:        | <b>Santa Cruz</b>                          |                 | Date:     | <b>06/28/2019</b>           |          |               |
| Building CAAN:    | <b>7822</b>                                | Auxiliary CAAN: | By Firm:  | <b>RUTHERFORD + CHEKENE</b> |          |               |
| Building Name:    | <b>Elena Baskin Visual Arts Building J</b> |                 | Initials: | <b>MN</b>                   | Checked: | <b>WAL/BL</b> |
| Building Address: | <b>Santa Cruz, CA 95064</b>                |                 | Page:     | <b>2</b>                    | of       | <b>3</b>      |

## ASCE 41-17 Collapse Prevention Basic Configuration Checklist

|  |   |
|--|---|
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> | <p>GEOMETRY: There are no changes in the net horizontal dimension of the seismic-force-resisting system of more than 30% in a story relative to adjacent stories, excluding one-story penthouses and mezzanines. (Commentary: Sec. A.2.2.5. Tier 2: Sec. 5.4.2.4)</p> <p><b>Comments:</b> Single story structure.</p> |
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> | <p>MASS: There is no change in effective mass of more than 50% from one story to the next. Light roofs, penthouses, and mezzanines need not be considered. (Commentary: Sec. A.2.2.6. Tier 2: Sec. 5.4.2.5)</p> <p><b>Comments:</b> Single story structure.</p>   |
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p>TORSION: The estimated distance between the story center of mass and the story center of rigidity is less than 20% of the building width in either plan dimension. (Commentary: Sec. A.2.2.7. Tier 2: Sec. 5.4.2.6)</p> <p><b>Comments:</b> Flexible diaphragm.</p>  |

### MODERATE SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR LOW SEISMICITY)

#### GEOLOGIC SITE HAZARD

|  | Description  |
|--|--|
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p>LIQUEFACTION: Liquefaction-susceptible, saturated, loose granular soils that could jeopardize the building's seismic performance do not exist in the foundation soils at depths within 50 ft (15.2m) under the building. (Commentary: Sec. A.6.1.1. Tier 2: 5.4.3.1)</p> <p><b>Comments:</b> Per 2009 County map at <a href="https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LiquifactionMap2009.pdf">https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LiquifactionMap2009.pdf</a></p>   |
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p>SLOPE FAILURE: The building site is located away from potential earthquake-induced slope failures or rockfalls so that it is unaffected by such failures or is capable of accommodating any predicted movements without failure. (Commentary: Sec. A.6.1.2. Tier 2: 5.4.3.1)</p> <p><b>Comments:</b> Per 2009 County map at <a href="https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LandslideMap2009.pdf">https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/LandslideMap2009.pdf</a></p> |
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p>SURFACE FAULT RUPTURE: Surface fault rupture and surface displacement at the building site are not anticipated. (Commentary: Sec. A.6.1.3. Tier 2: 5.4.3.1)</p> <p><b>Comments:</b> Per 2009 County map at <a href="https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/FaultZoneMap2009.pdf">https://gis.santacruzcounty.us/mapgallery/Emergency%20Management/Hazard%20Mitigation/FaultZoneMap2009.pdf</a></p>  |

**Note:** C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

|                   |                                     |                 |           |                      |          |        |
|-------------------|-------------------------------------|-----------------|-----------|----------------------|----------|--------|
| UC Campus:        | Santa Cruz                          |                 | Date:     | 06/28/2019           |          |        |
| Building CAAN:    | 7822                                | Auxiliary CAAN: | By Firm:  | RUTHERFORD + CHEKENE |          |        |
| Building Name:    | Elena Baskin Visual Arts Building J |                 | Initials: | MN                   | Checked: | WAL/BL |
| Building Address: | Santa Cruz, CA 95064                |                 | Page:     | 3                    | of       | 3      |

## ASCE 41-17 Collapse Prevention Basic Configuration Checklist

### HIGH SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR MODERATE SEISMICITY)

#### FOUNDATION CONFIGURATION

|                                  |                       |                       |                       | Description   |
|----------------------------------|-----------------------|-----------------------|-----------------------|---|
| <b>C</b>                         | <b>NC</b>             | <b>N/A</b>            | <b>U</b>              | <p>OVERTURNING: The ratio of the least horizontal dimension of the seismic-force-resisting system at the foundation level to the building height (base/height) is greater than <math>0.6S_a</math>. (Commentary: Sec. A.6.2.1. Tier 2: Sec. 5.4.3.3)</p> <p><b>Comments:</b><br/>           Least horizontal dimension of the seismic-force resisting system: <math>B = 40'-11 \frac{1}{2}"</math>,<br/>           Building Height: <math>H = 16'</math><br/> <math>B/H = 2.55</math><br/> <math>S_a = 1.281</math> per SEAOC at BSE-2E<br/> <math>0.6x S_a = 0.77</math><br/> <math>B/H &gt; 0.6 S_a \rightarrow OK</math></p> |
| <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> | <input type="radio"/> | <p>TIES BETWEEN FOUNDATION ELEMENTS: The foundation has ties adequate to resist seismic forces where footings, piles, and piers are not restrained by beams, slabs, or soils classified as Site Class A, B, or C. (Commentary: Sec. A.6.2.2. Tier 2: Sec. 5.4.3.4)</p> <p><b>Comments:</b> Site Class D is assumed. The slab-on-grade restrains strip footings.</p>   |

**Note:** C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

|                   |                                     |                 |  |           |                      |          |        |
|-------------------|-------------------------------------|-----------------|--|-----------|----------------------|----------|--------|
| UC Campus:        | Santa Cruz                          |                 |  | Date:     | 06/28/2019           |          |        |
| Building CAAN:    | 7822                                | Auxiliary CAAN: |  | By Firm:  | Rutherford + Chekene |          |        |
| Building Name:    | Elena Baskin Visual Arts Building J |                 |  | Initials: | MN                   | Checked: | WAL/BL |
| Building Address: | Santa Cruz, CA 95064                |                 |  | Page:     | 1                    | of       | 3      |

## ASCE 41-17 Collapse Prevention Structural Checklist For Building Type W2

### LOW AND MODERATE SEISMICITY

#### SEISMIC-FORCE-RESISTING SYSTEM

|   | Description  |                            |             |                    |           |                    |           |                      |         |
|---|--|----------------------------|-------------|--------------------|-----------|--------------------|-----------|----------------------|---------|
| <b>C NC N/A U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p>REDUNDANCY: The number of lines of shear walls in each principal direction is greater than or equal to 2. (Commentary: Sec. A.3.2.1.1. Tier 2: Sec. 5.5.1.1)</p> <p><b>Comments:</b> There are two lines of shear walls in each principal direction.</p>  |                            |             |                    |           |                    |           |                      |         |
| <b>C NC N/A U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p>SHEAR STRESS CHECK: The shear stress in the shear walls, calculated using the Quick Check procedure of Section 4.4.3.3, is less than the following values: (Commentary: Sec. A.3.2.7.1. Tier 2: Sec. 5.5.3.1.1)</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Structural panel sheathing</td> <td>1,000 lb/ft</td> </tr> <tr> <td>Diagonal sheathing</td> <td>700 lb/ft</td> </tr> <tr> <td>Straight sheathing</td> <td>100 lb/ft</td> </tr> <tr> <td>All other conditions</td> <td>100 /ft</td> </tr> </table> <p><b>Comments:</b></p> <ul style="list-style-type: none"> <li>- Average shear stress in N-S direction: 250 plf &lt; 1000 plf → OK</li> <li>- Average shear stress in E-W direction: 201 plf &lt; 1000 plf → OK</li> </ul> | Structural panel sheathing | 1,000 lb/ft | Diagonal sheathing | 700 lb/ft | Straight sheathing | 100 lb/ft | All other conditions | 100 /ft |
| Structural panel sheathing  | 1,000 lb/ft  |                            |             |                    |           |                    |           |                      |         |
| Diagonal sheathing  | 700 lb/ft  |                            |             |                    |           |                    |           |                      |         |
| Straight sheathing  | 100 lb/ft  |                            |             |                    |           |                    |           |                      |         |
| All other conditions  | 100 /ft  |                            |             |                    |           |                    |           |                      |         |
| <b>C NC N/A U</b><br><input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> | <p>STUCCO (EXTERIOR PLASTER) SHEAR WALLS: Multi-story buildings do not rely on exterior stucco walls as the primary seismic-force-resisting system. (Commentary: Sec. A.3.2.7.2. Tier 2: Sec. 5.5.3.6.1)</p> <p><b>Comments:</b> Single-story building.</p>  |                            |             |                    |           |                    |           |                      |         |
| <b>C NC N/A U</b><br><input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> | <p>GYPSUM WALLBOARD OR PLASTER SHEAR WALLS: Interior plaster or gypsum wallboard is not used for shear walls on buildings more than one story high with the exception of the uppermost level of a multi-story building. (Commentary: Sec. A.3.2.7.3. Tier 2: Sec. 5.5.3.6.1)</p> <p><b>Comments:</b> Single-story building.</p>  |                            |             |                    |           |                    |           |                      |         |
| <b>C NC N/A U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p>NARROW WOOD SHEAR WALLS: Narrow wood shear walls with an aspect ratio greater than 2-to-1 are not used to resist seismic forces. (Commentary: Sec. A.3.2.7.4. Tier 2: Sec. 5.5.3.6.1)</p> <p><b>Comments:</b> No narrow wood shear walls.</p>   |                            |             |                    |           |                    |           |                      |         |
| <b>C NC N/A U</b><br><input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> | <p>WALLS CONNECTED THROUGH FLOORS: Shear walls have an interconnection between stories to transfer overturning and shear forces through the floor. (Commentary: Sec. A.3.2.7.5. Tier 2: Sec. 5.5.3.6.2)</p> <p><b>Comments:</b> Single-story building.</p>   |                            |             |                    |           |                    |           |                      |         |
| <b>C NC N/A U</b><br><input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> | <p>HILLSIDE SITE: For structures that are taller on at least one side by more than one-half story because of a sloping site, all shear walls on the downhill slope have an aspect ratio less than 1-to-1. (Commentary: Sec. A.3.2.7.6. Tier 2: Sec. 5.5.3.6.3)</p> <p><b>Comments:</b> Site slope is smaller than one-half of a story height.</p>  |                            |             |                    |           |                    |           |                      |         |

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

|                   |                                     |                 |           |                      |          |        |
|-------------------|-------------------------------------|-----------------|-----------|----------------------|----------|--------|
| UC Campus:        | Santa Cruz                          |                 | Date:     | 06/28/2019           |          |        |
| Building CAAN:    | 7822                                | Auxiliary CAAN: | By Firm:  | Rutherford + Chekene |          |        |
| Building Name:    | Elena Baskin Visual Arts Building J |                 | Initials: | MN                   | Checked: | WAL/BL |
| Building Address: | Santa Cruz, CA 95064                |                 | Page:     | 2                    | of       | 3      |

## ASCE 41-17 Collapse Prevention Structural Checklist For Building Type W2

|  |   |
|--|---|
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> | <p>CRIPPLE WALLS: Cripple walls below first-floor-level shear walls are braced to the foundation with wood structural panels. (Commentary: Sec. A.3.2.7.7. Tier 2: Sec. 5.5.3.6.4)</p> <p><b>Comments:</b> No cripple walls.</p>  |
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> | <p>OPENINGS: Walls with openings greater than 80% of the length are braced with wood structural panel shear walls with aspect ratios of not more than 1.5-to-1 or are supported by adjacent construction through positive ties capable of transferring the seismic forces. (Commentary: Sec. A.3.2.7.8. Tier 2: Sec. 5.5.3.6.5)</p> <p><b>Comments:</b> No large openings observed in wood shear walls.</p>   |
| <b>CONNECTIONS</b>   |   |
|  | <b>Description</b>  |
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p>WOOD POSTS: There is a positive connection of wood posts to the foundation. (Commentary: Sec. A.5.3.3. Tier 2: Sec. 5.7.3.3)</p> <p><b>Comments:</b><br/>4x6 wood posts on the south side of the building are positively connected to the footing with HD2A ties per structural drawings, Sheet S-2. The connection detail for other wood posts is not specifically called out but is assumed similar.</p> |
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p>WOOD SILLS: All wood sills are bolted to the foundation. (Commentary: Sec. A.5.3.4. Tier 2: Sec. 5.7.3.3)</p> <p><b>Comments:</b><br/>All wood sills are bolted to the foundation with 5/8" <math>\Phi</math> A.B. @ 32" o.c.</p>  |
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p>GIRDER/COLUMN CONNECTION: There is a positive connection using plates, connection hardware, or straps between the girder and the column support. (Commentary: Sec. A.5.4.1. Tier 2: Sec. 5.7.4.1)</p> <p><b>Comments:</b><br/>There is a positive connection between the girder and the column support per Details 7- and 15-S4.</p>   |

### HIGH SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR LOW AND MODERATE SEISMICITY)

|  |   |
|--|---|
| <b>CONNECTIONS</b>   |   |
|  | <b>Description</b>  |
| <b>C</b> <b>NC</b> <b>N/A</b> <b>U</b><br><input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> | <p>WOOD SILL BOLTS: Sill bolts are spaced at 6 ft (1.8 m) or less with acceptable edge and end distance provided for wood and concrete. (Commentary: A.5.3.7. Tier 2: Sec. 5.7.3.3)</p> <p><b>Comments:</b> All wood sills are bolted to the foundation with 5/8" <math>\Phi</math> A.B. @ 32" o.c. and 9" from the ends per 4/S-1.</p> |

|                   |                                     |                 |  |           |                      |          |        |
|-------------------|-------------------------------------|-----------------|--|-----------|----------------------|----------|--------|
| UC Campus:        | Santa Cruz                          |                 |  | Date:     | 06/28/2019           |          |        |
| Building CAAN:    | 7822                                | Auxiliary CAAN: |  | By Firm:  | Rutherford + Chekene |          |        |
| Building Name:    | Elena Baskin Visual Arts Building J |                 |  | Initials: | MN                   | Checked: | WAL/BL |
| Building Address: | Santa Cruz, CA 95064                |                 |  | Page:     | 3                    | of       | 3      |

## ASCE 41-17 Collapse Prevention Structural Checklist For Building Type W2

| DIAPHRAGMS                       |                                  |                                  |                       |   |  |  |  |
|----------------------------------|----------------------------------|----------------------------------|-----------------------|---|--|--|--|
|                                  |                                  |                                  |                       | Description   |  |  |  |
| <b>C</b>                         | <b>NC</b>                        | <b>N/A</b>                       | <b>U</b>              | DIAPHRAGM CONTINUITY: The diaphragms are not composed of split-level floors and do not have expansion joints. (Commentary: Sec. A.4.1.1. Tier 2: Sec. 5.6.1.1)<br><br><b>Comments:</b> The entire roof is composed of 6 plan-rectangular individual sawtooth segments. Sheet S3 shows that the load generated in the NE-SW direction at individual segments is transferred at short sides directly to perimeter shear walls. Aspect ratios within the segments range from 3:1 to about 6.5:1, but struts connect the top and bottom edges of the segments and will help link segments together. In the NW-SE direction tension tie rods link the wood header at the top of one segment to the glulam at the bottom of another segment. Evaluation of adequacy is beyond the scope of the Tier 1 evaluation. |  |  |  |
| <input type="radio"/>            | <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/> |   |  |  |  |
| <b>C</b>                         | <b>NC</b>                        | <b>N/A</b>                       | <b>U</b>              | ROOF CHORD CONTINUITY: All chord elements are continuous, regardless of changes in roof elevation. (Commentary: Sec. A.4.1.3. Tier 2: Sec. 5.6.1.1)<br><br><b>Comments:</b> Per Details 2,4/S3, short sides of sawtooth roof segments connect to continuous sloping double top plates. Per Details 1,3/S3, long sides of sawtooth roof segments connect to continuous 4x headers or to 6 3/4 glulam beams with tie rods spanning between the header and glulam. There is no defined chord at the bottom level of the sawtooth segment in the perimeter walls.   |  |  |  |
| <input type="radio"/>            | <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/> |   |  |  |  |
| <b>C</b>                         | <b>NC</b>                        | <b>N/A</b>                       | <b>U</b>              | DIAPHRAGM REINFORCEMENT AT OPENINGS: There is reinforcing around all diaphragm openings larger than 50% of the building width in either major plan dimension. (Commentary: Sec. A.4.1.8. Tier 2: Sec. 5.6.1.5)<br><br><b>Comments:</b> No large opening observed in the roof diaphragm (except for the clerestory windows covered by other checklist questions).  |  |  |  |
| <input type="radio"/>            | <input type="radio"/>            | <input checked="" type="radio"/> | <input type="radio"/> |   |  |  |  |
| <b>C</b>                         | <b>NC</b>                        | <b>N/A</b>                       | <b>U</b>              | STRAIGHT SHEATHING: All straight-sheathed diaphragms have aspect ratios less than 2-to-1 in the direction being considered. (Commentary: Sec. A.4.2.1. Tier 2: Sec. 5.6.2)<br><br><b>Comments:</b> 3/4" plywood per S-3.  |  |  |  |
| <input type="radio"/>            | <input type="radio"/>            | <input checked="" type="radio"/> | <input type="radio"/> |   |  |  |  |
| <b>C</b>                         | <b>NC</b>                        | <b>N/A</b>                       | <b>U</b>              | SPANS: All wood diaphragms with spans greater than 24 ft (7.3 m) consist of wood structural panels or diagonal sheathing. (Commentary: Sec. A.4.2.2. Tier 2: Sec. 5.6.2)<br><br><b>Comments:</b> All wood diaphragms consist of wood structural panels (3/4" plywood per S3.)   |  |  |  |
| <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/>            | <input type="radio"/> |   |  |  |  |
| <b>C</b>                         | <b>NC</b>                        | <b>N/A</b>                       | <b>U</b>              | DIAGONALLY SHEATHED AND UNBLOCKED DIAPHRAGMS: All diagonally sheathed or unblocked wood structural panel diaphragms have horizontal spans less than 40 ft (12.2 m) and have aspect ratios less than or equal to 4-to-1. (Commentary: Sec. A.4.2.3. Tier 2: Sec. 5.6.2)<br><br><b>Comments:</b> Unblock wood structural panel diaphragm at canopy has horizontal span less than 40 ft and have aspect ratio less than or equal to 4-to-1. The main roof diaphragm is blocked.  |  |  |  |
| <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/>            | <input type="radio"/> |   |  |  |  |
| <b>C</b>                         | <b>NC</b>                        | <b>N/A</b>                       | <b>U</b>              | OTHER DIAPHRAGMS: The diaphragms do not consist of a system other than wood, metal deck, concrete, or horizontal bracing. (Commentary: Sec. A.4.7.1. Tier 2: Sec. 5.6.5)<br><br><b>Comments:</b> All wood diaphragms consist of wood structural panels (3/4" plywood per S3.)   |  |  |  |
| <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/>            | <input type="radio"/> |   |  |  |  |

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown



---

## **APPENDIX C**

# **UCOP Seismic Safety Policy Falling Hazards Assessment Summary**

|                   |                                     |                 |           |                      |          |        |
|-------------------|-------------------------------------|-----------------|-----------|----------------------|----------|--------|
| UC Campus:        | Santa Cruz                          |                 | Date:     | 06/28/2019           |          |        |
| Building CAAN:    | 7822                                | Auxiliary CAAN: | By Firm:  | Rutherford + Chekene |          |        |
| Building Name:    | Elena Baskin Visual Arts Building J |                 | Initials: | MN                   | Checked: | WAL/BL |
| Building Address: | Santa Cruz, CA 95064                |                 | Page:     | 1                    | of       | 1      |

## UCOP SEISMIC SAFETY POLICY Falling Hazard Assessment Summary

|  | Description  |
|--|--|
| <p><b>P</b>   <b>N/A</b><br/> <input type="checkbox"/>   <input checked="" type="checkbox"/></p> | <p>Heavy ceilings, features or ornamentation above large lecture halls, auditoriums, lobbies, or other areas where large numbers of people congregate (50 ppl or more)</p> <p><b>Comments:</b> There are no heavy ceilings, features or ornamentation above the painting studio.</p> |
| <p><b>P</b>   <b>N/A</b><br/> <input type="checkbox"/>   <input checked="" type="checkbox"/></p> | <p>Heavy masonry or stone veneer above exit ways or public access areas</p> <p><b>Comments:</b> Masonry or stone veneer is not present in this building.</p>   |
| <p><b>P</b>   <b>N/A</b><br/> <input type="checkbox"/>   <input checked="" type="checkbox"/></p> | <p>Unbraced masonry parapets, cornices, or other ornamentation above exit ways or public access areas</p> <p><b>Comments:</b> Masonry is not present in this building.</p>   |
| <p><b>P</b>   <b>N/A</b><br/> <input type="checkbox"/>   <input checked="" type="checkbox"/></p> | <p>Unrestrained hazardous material storage</p> <p><b>Comments:</b> No hazardous material storage was observed.</p>   |
| <p><b>P</b>   <b>N/A</b><br/> <input type="checkbox"/>   <input checked="" type="checkbox"/></p> | <p>Masonry chimneys</p> <p><b>Comments:</b> Masonry is not present in this building.</p>   |
| <p><b>P</b>   <b>N/A</b><br/> <input type="checkbox"/>   <input checked="" type="checkbox"/></p> | <p>Unrestrained natural gas-fueled equipment such as water heaters, boilers, emergency generators, etc.</p> <p><b>Comments:</b> Equipment featured cable bracing.</p>  |
| <p><b>P</b>   <b>N/A</b><br/> <input checked="" type="checkbox"/>   <input type="checkbox"/></p> | <p>Other:</p> <p><b>Comments:</b></p>  |
| <p><b>P</b>   <b>N/A</b><br/> <input type="checkbox"/>   <input type="checkbox"/></p>            | <p>Other:</p> <p><b>Comments:</b></p>  |
| <p><b>P</b>   <b>N/A</b><br/> <input type="checkbox"/>   <input type="checkbox"/></p>            | <p>Other:</p> <p><b>Comments:</b></p>  |

Falling Hazards Risk: **Low**





---

## APPENDIX D

### Quick Check Calculations



## Unit Weights:

|                               | Seismic Weight | Dead Load |  |
|-------------------------------|----------------|-----------|--|
|                               | psf            | psf       | Remarks  |
| <b>Main Roof</b>              |                |           |  |
| Roofing                       | 3              | 3         | Metal roof per arch. Dwg.; Product specification not available |
| Sheathing Board               | 2.1            | 2.1       | 3/4" plywood   |
| Rafter                        | 1.0            | 1.0       | 2x6 @ 2' o.c.  |
| Ceiling                       | 2              | 2         | typ. gypboard ceiling panels                                   |
| Lighting and misc.            | 5              | 5         |  |
| Columns                       | 0.468          | 0.468     |  |
| Beams                         | 5.563          | 5.563     | Glu-lam beams  |
| Partition+Plywood shear walls | 7.5            | 7.5       | Half of 15 psf   |
| <b>Total</b>                  | <b>27</b>      | <b>27</b> |  |

|                    | Seismic Weight | Dead Load |  |
|--------------------|----------------|-----------|--|
|                    | psf            | psf       | Remarks  |
| <b>Canopy Roof</b> |                |           |  |
| Roofing            | 2              | 2         | Modified Bitumen Roofing per arch. Dwg.; Product specification not available |
| Sheathing Board    | 1.4            | 1.4       | 1/2" plywood   |
| Rafter             | 2.0            | 2.0       | 2x6 @ 1' o.c.  |
| Ceiling            | 2              | 2         | 1x6 T&G siding (at 36 pcf)   |
| Columns            | 0.908          | 0.908     | 2 1/2" STD pipe  |
| misc.+lighting     | 2.0            | 2.0       | Half of 15 psf   |
| <b>Total</b>       | <b>10</b>      | <b>10</b> |  |



## Story Weights

| Floor Levels                 | Floor Area (ft <sup>2</sup> ) | Floor Weight (psf) | Additional Weight (kips) | Total Seismic Weight (kips) |
|------------------------------|-------------------------------|--------------------|--------------------------|-----------------------------|
| Main Roof                    | 2,042                         | 27                 |                          | 54                          |
| Canopy                       | 83                            | 10                 |                          | 1                           |
| <b>Total Weight (kips) =</b> |                               |                    |                          | <b>55</b>                   |

Notes:

1 - Seismic base is set at the 1st floor. Soil-structure interaction is ignored for ASCE 41-17 Tier 1.

## Period

|                           |       |
|---------------------------|-------|
| $C_t =$                   | 0.02  |
| $h_n$ (ft) <sup>1</sup> = | 16.08 |
| $B =$                     | 0.75  |

1 - Average of the low and high point of the sloped roof

|       |      |     |
|-------|------|-----|
| $T =$ | 0.16 | sec |
|-------|------|-----|

Notes:

1- The period calculated per ASCE 41-17 Equation 4-4.

$$T = C_t \cdot h_n^B$$

2-  $C_t$  and  $B$  are for "all other framing system" per ASCE 41-17 Section 4.4.2.4.

3- The building height is taken from the 1st floor to the roof.



# BSE-2E Response Spectrum

6/10/2019

U.S. Seismic Design Maps



Latitude, Longitude: 36.994360, -122.060200



|                                |                                  |
|--------------------------------|----------------------------------|
| Date                           | 6/10/2019, 10:51:30 AM           |
| Design Code Reference Document | ASCE41-17                        |
| Custom Probability             |                                  |
| Site Class                     | D - Default (See Section 11.4.3) |

| Type         | Description                             | Value  |
|--------------|---|--------|
| Hazard Level |   | BSE-2E |
| $S_s$        | spectral response (0.2 s)               | 1.281  |
| $S_1$        | spectral response (1.0 s)               | 0.485  |
| $S_{XS}$     | site-modified spectral response (0.2 s) | 1.537  |
| $S_{X1}$     | site-modified spectral response (1.0 s) | 0.881  |
| $f_a$        | site amplification factor (0.2 s)       | 1.2    |
| $f_v$        | site amplification factor (1.0 s)       | 1.815  |



## Story Shears

|     |       |                      |
|-----|-------|----------------------|
| Sa= | 1.281 |                      |
| W=  | 55    | kips                 |
| C=  | 1.3   | ASCE 41-17 Table 4-7 |

1 - Modification Factor, C, per ASCE 41-17, Table 4-7 for single story W2 shear wall building type is used.

|    |    |      |
|----|----|------|
| V= | 92 | kips |
|----|----|------|

|    |      |  |
|----|------|--|
| k= | 1.00 |  |
|----|------|--|

| Floor Levels | Story Height<br>(ft) | Total Height, H<br>(ft) | Weight, W<br>(kips) | W x H <sup>k</sup> | coeff | Fx<br>(kips) | Story Shear, V<br>(kips) |
|--------------|----------------------|-------------------------|---------------------|--------------------|-------|--------------|--------------------------|
| Main Roof    | 16.08                | 16.08                   | 55                  | 889                | 1.00  | 92           | 92                       |
|              |                      |                         |                     | 889                | 1     | 92           |                          |

Notes:

1- The base of building is assumed to be at the 1st floor.



# Average Stress in Wood-framed Wall

**Average Stresses**

Ms = 4.5

| Direction     | Story Shear<br>(kips) | Wall Length<br>(ft) | Opening ratio | Average Shear<br>Stress<br>(plf) | Tier 1 Shear<br>Stress Limit<br>(plf) | Wall OK? |
|---------------|-----------------------|---------------------|---------------|----------------------------------|---------------------------------------|----------|
| E-W direction | 92                    | 102                 | 1.00          | 184                              | 1000                                  | OK       |
| N-S direction | 92                    | 82                  | 1.00          | 229                              | 1000                                  | OK       |